

## JUDIQUE DAM

- Drain Valve is broken and needs to be repaired at the bottom.
- There is a build-up of silt and debris at the bottom of the dam, and we have been unable to alleviate this due to the drain valve being broken.
- Work had been done in the summer of 2013 to repair the inlet piping and install a concrete shield to protect the piping at the dam.
- The dam is 10m wide by 3m high and was constructed in 1973 (by Zutphen Bros if I read the tender document correctly). I can not find any other specs on the dam.



